

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Office of Cultural Affairs

For HPD Office use only: HCPI No. District No. NRHP: SRCP: Criteria: A B C D

NAME OF PROPERTY: **Bent St 134 - Trujillo House**

LOCAL REFERENCE NUMBER: **2005011**

LOCATION OF PROPERTY: **132 BENT**

UTM ZONE:

CITY OR TOWN: **Taos**

UTM EASTING:

COUNTY: **Taos**

UTM NORTHING:

DATE OF SURVEY:

2/18/2005

PREVIOUS SURVEY?

Not Available

PREVIOUS SURVEY DATE:

Not Available

NAME OF PROJECT:

2005 CLG Survey

PHOTOGRAPH:

ROLL NUMBER:

FRAME NUMBER:

NEGATIVE LOCATION:



PROPERTY TYPE: **Primary**

PHOTOGRAPH VIEW: **2005 Survey Photo 1**

DESCRIPTION OF PROPERTY:

132-134 Bent Street is a single story painted stucco on adobe former residential building with a low cross-hip roofline covered with blue propanel. Its paint scheme includes white on the upper areas of the wall and brown at the lower areas in an undulating pattern. The walls are pattered and curve inwards at the gable roof eaves. Windows are fixed undivided plate glass units with metal grilles. Doors are single leaf glass and wood units providing access to the various commercial spaces inside. The building sits at the street edge on the north and adjacent to a large parking lot on the south. A centrally-located painted stucco yard wall runs along the north property line east and connects this building with #130 Bent to the east. It too shares the paint scheme of the building. A flagstone patio exists in the open area between the structures. An additional low stuccoed yard wall encloses the property on the east.

CONSTRUCTION DATE KNOWN? **Yes** SOURCE FOR CONSTRUCTION DATE: **PETER MACKANESS**

CONSTRUCTION DATE: **-1 to 1908**

SIGNIFICANT MODIFICATIONS? **1939-1957 addition of east wing, post-1957 cross-hip roof and removal of building portion on north adjacent to street, new windows, infilled door on north elevation,**

NOTES ON CONDITION: **Good**

WHO USES THE PROPERTY?: **Wild Life Clothing Co., Mud-n-Flood Mountain Shop**

SETTING: **Urban**

RELATIONSHIP TO SURROUNDINGS: **Similar**

IF URBAN SETTING, NATURE OF IT:

COMMENTS ON SURROUNDINGS:

ADDITIONAL PERSPECTIVE: (Photo, drawing, footprint, etc.; indicate north arrow when possible)



NOTES ON ADDITIONAL PERSPECTIVE: **south elevation**
 (If photo, include photo info, as in #10)

SURVEYOR BUSINESS NAME: **Ragins Research and Planning**
 SURVEYOR FIRST NAME: **Mary**
 SURVEYOR LAST NAME: **Ragins**
 SURVEYOR STREET ADDRESS: **9 Stone ridge Road**
 SURVEYOR CITY: **Santa Fe**

OWNER OR OTHER KNOWLEDGEABLE PEOPLE:
PETER MACKANESS

SURVEYOR ZIP CODE: **87505**
 SURVEYOR TELEPHONE: **575.995.0852**
 SURVEYOR EMAIL:

IS THE PROPERTY ENDANGERED?: **NO**
 HOW IS THE PROPERTY ENDANGERED?:

The 1915 Joy Survey identified the property as owned by Virginia R. Trujillo with a structure on it. This structure appears on the 1908 Sanborn Map. The 1908 - 1939 Sanborn Maps reflect a linear building that ran east-west at the north property line on Bent Lane [Street]. The 1957 NM DOT aerial shows this same form with the

SIGNIFICANCE TO CURRENT COMMUNITY: **Low**

DESCRIPTION OF COMMUNITY SIGNIFICANCE: **strong historic associations but eroded architectural integrity with modern ro**

OTHER INFORMATION OF INTEREST: (Such as historical, legendary, structural, former ownership, etc.)

The 1915 Joy Survey identified the property as owned by Virginia R. Trujillo with a structure on it. This structure appears on the 1908 Sanborn Map. The 1908 - 1939 Sanborn Maps reflect a linear building that ran east-west at the north property line on Bent Lane [Street]. The 1957 NM DOT aerial shows this same form with the addition of the existing southeast wing. At some point after 1957, a portion of the building was removed. The current open courtyard to the west of #130 Bent Street and this structure is the location of this removed mass. It is likely that the existing yard wall along Bent Street was once part of this building mass that was removed. The building was surveyed in 1981 as # 022503006. It is on Tract 348 # 1-074-149-329-009.

Construction Date From: Sanborn Map

Individual Building Status

IS PROPERTY INDIVIDUALLY LISTED ON A REGISTER?:

INDIVIDUALLY LISTED ON SRCP?: **NO**

INDIVIDUALLY LISTED ON NRHP?: **NO**

IF NOT LISTED, IS IT ELIGIBLE?:

IF ELIGIBLE, WHY?:

Building Located In A Special Historic District?

IS PROPERTY IN SPECIAL HISTORIC DISTRICT? **YES**
 DISTRICT NAME AND STATUS:

Taos Downtown Historic District - SRCP **YES**

La Loma Plaza Historic District - SRCP **NO**

Taos Historic Overlay Zone - Taos Only **YES**

Historic Cultural Properties Inventory (HCPI) Detail Form (Form 2)

Historic Preservation Division, New Mexico Office of Cultural Affairs >>Complete HCPI Form 1 before Form 2<<

For HPD Office use only: HCPI No. District No. LOCAL REFERENCE NUMBER: 2005011
NAME OF PROPERTY: Bent St 134 - Trujillo House LOCATION OF PROPERTY: 132 BENT
COUNTY: Taos CITY OR TOWN: Taos DATE OF SURVEY: 2/18/2005

ARCHITECTURAL AND CONSTRUCTION DETAILS

STORIES ABOVE GRADE? 1.0

CONSTRUCTION MATERIAL:

PRIMARY VISIBLE CONSTRUCTION MATERIAL:

NOTES ON VISIBLE CONSTRUCTION MATERIAL: Its paint scheme includes white on the upper areas of the wall and brown at the l

FOUNDATION:

DOES A FOUNDATION EXIST?:

TYPE OF FOUNDATION:

FOUNDATION MATERIALS

FOUNDATION NOTES:

GENERAL: Notes

Details

vertical stucco cracking at northeast corner, otherwise well maintained

EXTERIOR: Notes

Details

Its paint scheme includes white on the upper areas of the wall and brown at the lower areas in an undulating pattern. The walls are battered and curve inwards at the gable roof eaves.

Patio

ROOF: Notes

Details

low cross-hip roofline, blue metal roofing.

Gabled
Low

DOORS: Notes

Details

Glass
Wood

WINDOWS: Notes

Details

Glazed
Fixed
Metal grills
Undivided

PORCHES/PORTALES: Notes

Details

Not Available

CHIMNEYS: Notes

Details

Not Available

EXTERIOR WALLS : Notes

Details

A centrally-located painted stucco yard wall runs along the north property line east and connects this building with #130 Bent to the east.

Stucco

LANDSCAPING: Notes

Details

Not Available

LOCAL REFERENCE NUMBER:

OTHER SIGNIFICANT FEATURES Describe unique features.)

[Empty box for other significant features]

MODIFICATIONS: (For each entry, indicate source of the date. Enter "surveyor" if it is your own. If prior survey, give date.)

[Empty box for modifications]


PRIMARY ARCHITECTURAL STYLE:

vertical stucco cracking at northeast corner, otherwise well maintained

Spanish-Pueblo Revival

SITE PLAN:

(Include footprint of building, porches and balconies, major landscape features, associated properties, walls, fences, gates, nearby roads, driveways, and north arrow.)



LOCATION OF, AND AVAILABLE DOCUMENTS

(Plans, histories, oral histories, maps, aerial photos, bibliographic references, etc. and where they can be found.)

[Empty box for location of documents]

SITE PLAN NOTES:

Site. Base map provided by Taos GIS. NTS.

ATTACHED OR ASSOCIATED PROPERTIES:

(List and describe. Indicate whether surveys exist for these and provide survey numbers if known.)

DESCRIPTION OF ATTACHED OR ASSOCIATED PROPERTIES:

The 1915 Joy Survey identified the property as owned by Virginia R. Trujillo with a structure on it. This structure appears on the 1908 Sanborn Map. The 1908 - 1939 Sanborn Maps refle

IF SO, ARE THEY ELIGIBLE FOR LISTING?: None



2005 Survey Photo 3