

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Office of Cultural Affairs

For HPD Office use only: HCPI No. District No. NRHP: SRCP: Criteria: A B C D

NAME OF PROPERTY: **Paseo del Pueblo Norte 220 - First Baptist Church** LOCAL REFERENCE NUMBER: **2005021**
LOCATION OF PROPERTY: **220 PASEO DEL PUEBLO NORTE** UTM ZONE:
CITY OR TOWN: **Taos** UTM EASTING:
COUNTY: **Taos** UTM NORTHING:

DATE OF SURVEY:
2/19/2005
PREVIOUS SURVEY?
Not Available

PREVIOUS SURVEY DATE:
Not Available

NAME OF PROJECT:
2005 CLG Survey

PHOTOGRAPH:
ROLL NUMBER:

FRAME NUMBER:

NEGATIVE LOCATION:



PROPERTY TYPE: **Primary** PHOTOGRAPH VIEW: **south elevation from west showing post-1957 roofline of rear building**

DESCRIPTION OF PROPERTY:

220 Paseo del Pueblo Norte is a two-story combined Spanish Pueblo–Mission Revival style religious structure with pink-hued stucco. It has a corner tower and flat parapet which conceals the building's gable roof line. Windows are wooden stationary 9-lite units with upper and lower 3-lite hopper units on the east elevation. Along the south elevation and in the rear additions, the windows are wooden 1-over-1 double hung units. Exposed lintels cap each window. There is a double-leaf wood panel door on the east which provides access to the building. A secondary entrance on the south elevation includes a single-leaf wooden unit with sidelights. The simple tower at the building's northeast corner has openings filled with jigsaw-cut grilles. There is a centrally-hung cross on the upper east elevation. The building is buttressed on the south and north. A low stuccoed yard wall creates an entry court on the east. The detached rear building has a low-gabled roof and multi-lite casement window units.

CONSTRUCTION DATE KNOWN? **Yes** SOURCE FOR CONSTRUCTION DATE:

CONSTRUCTION DATE: to

SIGNIFICANT MODIFICATIONS?

NOTES ON CONDITION:

WHO USES THE PROPERTY?:

SETTING: **Urban**

RELATIONSHIP TO SURROUNDINGS **Dissimilar**

IF URBAN SETTING, NATURE OF IT:

COMMENTS ON SURROUNDINGS:

Commercial

ADDITIONAL PERSPECTIVE: (Photo, drawing, footprint, etc.; indicate north arrow when possible)



NOTES ON ADDITIONAL PERSPECTIVE: east and south elevations
(If photo, include photo info, as in #10)

SURVEYOR BUSINESS NAME: Ragins Research and Planning

OWNER OR OTHER KNOWLEDGEABLE PEOPLE:

SURVEYOR FIRST NAME: Mary

SURVEYOR LAST NAME:

SURVEYOR STREET ADDRESS:

IS THE PROPERTY ENDANGERED?: NO

SURVEYOR CITY:

HOW IS THE PROPERTY ENDANGERED?:

SURVEYOR ZIP CODE:

SURVEYOR TELEPHONE:

SURVEYOR EMAIL:

SIGNIFICANCE TO CURRENT COMMUNITY:

DESCRIPTION OF COMMUNITY SIGNIFICANCE:

OTHER INFORMATION OF INTEREST: (Such as historical, legendary, structural, former ownership, etc.)

Individual Building Status

IS PROPERTY INDIVIDUALLY LISTED ON A REGISTER?:

INDIVIDUALLY LISTED ON SRCP?: NO

INDIVIDUALLY LISTED ON NRHP?: NO

IF NOT LISTED, IS IT ELIGIBLE?:

IF ELIGIBLE, WHY?:

Building Located In A Special Historic District?

IS PROPERTY IN SPECIAL HISTORIC DISTRICT? YES

DISTRICT NAME AND STATUS:

Taos Downtown Historic District - SRCP NO

La Loma Plaza Historic District - SRCP NO

Taos Historic Overlay Zone - Taos Only YES

Historic Cultural Properties Inventory (HCPI) Detail Form (Form 2)

Historic Preservation Division, New Mexico Office of Cultural Affairs >>Complete HCPI Form 1 before Form 2<<

For HPD Office use only: HCPI No. District No. LOCAL REFERENCE NUMBER: 2005021

NAME OF PROPERTY: Paseo del Pueblo Norte 220 - First Baptist Church LOCATION OF PROPERTY: 220 PASEO DEL PUEBLO NOR
COUNTY: Taos CITY OR TOWN: Taos DATE OF SURVEY: 2/19/2005

ARCHITECTURAL AND CONSTRUCTION DETAILS

STORIES ABOVE GRADE? 2.0

CONSTRUCTION MATERIAL:

PRIMARY VISIBLE CONSTRUCTION MATERIAL:

NOTES ON VISIBLE CONSTRUCTION MATERIAL: The simple tower at the building's northeast corner has openings filled with jigs

FOUNDATION:

" Not Available"

GENERAL: Notes

Details

" Not Available"

EXTERIOR: Notes

Details

The simple tower at the building's northeast corner has openings filled with jigsaw-cut grilles. There is a centrally-hung cross on the upper east elevation. The building is buttressed on the south and north. A low stuccoed yard wall creates an entry court on the east.

Buttresses

Details

**Flat Parapet
Gabled
Low**

ROOF: Notes

DOORS: Notes

Details

single-leaf wooden unit with sidelights.

**Wood
Glass
Windows/Lites**

WINDOWS: Notes

Details

1 over 1 double hung units

**Fixed
Divided Light
Double Hung
Exposed lintels**

PORCHES/PORTALES: Notes

Details

Not Available

CHIMNEYS: Notes

Details

Not Available

EXTERIOR WALLS : Notes

Details

Not Available

LANDSCAPING: Notes

Details

Not Available

OTHER SIGNIFICANT FEATURES *Describe unique features.*

[Empty box for other significant features]

MODIFICATIONS: *(For each entry, indicate source of the date. Enter "surveyor" if it is your own. If prior survey, give date.)*

[Empty box for modifications]


PRIMARY ARCHITECTURAL STYLE:

single story commercial corridor

Spanish-Pueblo Revival

SITE PLAN:

(Include footprint of building, porches and balconies, major landscape features, associated properties, walls, fences, gates, nearby roads, driveways, and north arrow.)



LOCATION OF, AND AVAILABLE DOCUMENTS

(Plans, histories, oral histories, maps, aerial photos, bibliographic references, etc. and where they can be found.)

[Empty box for location of documents]

SITE PLAN NOTES:

Site. Base map provided by Taos GIS. NTS.

ATTACHED OR ASSOCIATED PROPERTIES: *(List and describe. Indicate whether surveys exist for these and provide survey numbers if known.)*

DESCRIPTION OF ATTACHED OR ASSOCIATED PROPERTIES

The structure was surveyed in 1981 as #022503035. It is on Tract 195 #1-074-149-422-092.

Construction Date From: 1957 NM DOT aerial photo

IF SO, ARE THEY ELIGIBLE FOR LISTING?: None