

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Office of Cultural Affairs

For HPD Office use only: HCPI No. District No. NRHP: SRCP: Criteria: A B C D

NAME OF PROPERTY: **Don Fernando St 305 A - Enos Garcia Elementary School**

LOCAL REFERENCE NUMBER: **2005059**

LOCATION OF PROPERTY:

UTM ZONE:

CITY OR TOWN:

UTM EASTING:

COUNTY:

Taos

UTM NORTHING:

DATE OF SURVEY:

3/12/2005

PREVIOUS SURVEY?

Not Available

PREVIOUS SURVEY DATE:

Not Available

NAME OF PROJECT:

2005 CLG Survey

PHOTOGRAPH:

ROLL NUMBER:

FRAME NUMBER:

NEGATIVE LOCATION:



PROPERTY TYPE: **Primary**

PHOTOGRAPH VIEW: **north elevation**

DESCRIPTION OF PROPERTY:

305 Don Fernando Street is a single story earth-toned stuccoed Spanish Pueblo Revival style public school building with a flat parapet and canales. Windows are wooden 6-over-6 and 8-over-8 double-hung units with snap-in muntins on the south, east, and west elevations. At the locations of these modern units, the sills which supported the original units "float" on the building walls. On the north elevation, in the area of the post-1957 addition, windows are multi-lite steel units which have been sealed so that they no longer operate. The main entrance on the south is a deeply recessed raised area with lintels, corbels, and vigas. The door is a wide double-leaf metal unit with a large area of undivided glass, and a stationary transom window. Partial-width narrow portales at the building's northwest and northeast corners have posts, corbels, and exposed lintels; they mark secondary entrances into the building. Additionally, there is a large access ramp with pipe railings at the building's southeast corner. Asphalt parking and student drop off areas stand at the building's north and east side. Chain link fencing and low

CONSTRUCTION DATE KNOWN? **Yes** SOURCE FOR CONSTRUCTION DATE:

CONSTRUCTION DATE: to

SIGNIFICANT MODIFICATIONS?

NOTES ON CONDITION:

WHO USES THE PROPERTY?:

SETTING: **Urban**

RELATIONSHIP TO SURROUNDINGS **Similar**

IF URBAN SETTING, NATURE OF IT:

COMMENTS ON SURROUNDINGS:

ADDITIONAL PERSPECTIVE: (Photo, drawing, footprint, etc.; indicate north arrow when possible)



NOTES ON ADDITIONAL PERSPECTIVE: east elevation
(If photo, include photo info, as in #10)

SURVEYOR BUSINESS NAME: Ragins Research and Planning

OWNER OR OTHER KNOWLEDGEABLE PEOPLE:

SURVEYOR FIRST NAME: Mary

SURVEYOR LAST NAME:

SURVEYOR STREET ADDRESS:

IS THE PROPERTY ENDANGERED?: NO

SURVEYOR CITY:

HOW IS THE PROPERTY ENDANGERED?:

SURVEYOR ZIP CODE:

SURVEYOR TELEPHONE:

SURVEYOR EMAIL:

SIGNIFICANCE TO CURRENT COMMUNITY:

DESCRIPTION OF COMMUNITY SIGNIFICANCE:

OTHER INFORMATION OF INTEREST: (Such as historical, legendary, structural, former ownership, etc.)

Individual Building Status

IS PROPERTY INDIVIDUALLY LISTED ON A REGISTER?:

INDIVIDUALLY LISTED ON SRCP?: NO

INDIVIDUALLY LISTED ON NRHP?: NO

IF NOT LISTED, IS IT ELIGIBLE?:

IF ELIGIBLE, WHY?:

Building Located In A Special Historic District?

IS PROPERTY IN SPECIAL HISTORIC DISTRICT? YES

DISTRICT NAME AND STATUS:

Taos Downtown Historic District - SRCP NO

La Loma Plaza Historic District - SRCP NO

Taos Historic Overlay Zone - Taos Only YES

Historic Cultural Properties Inventory (HCPI) Detail Form (Form 2)

Historic Preservation Division, New Mexico Office of Cultural Affairs >>Complete HCPI Form 1 before Form 2<<

For HPD Office use only: HCPI No. District No. LOCAL REFERENCE NUMBER: 2005059

NAME OF PROPERTY: Don Fernando St 305 A - Enos Garcia Elementary LOCATION OF PROPERTY:

COUNTY: Taos

CITY OR TOWN:

DATE OF SURVEY: 3/12/2005

ARCHITECTURAL AND CONSTRUCTION DETAILS

STORIES ABOVE GRADE? 1.0

CONSTRUCTION MATERIAL:

PRIMARY VISIBLE CONSTRUCTION MATERIAL:

NOTES ON VISIBLE CONSTRUCTION MATERIAL: **Additionally, there is a large access ramp with pipe railings at the building's sou**

FOUNDATION:

DOES A FOUNDATION EXIST?:

TYPE OF FOUNDATION:

FOUNDATION MATERIALS **General**

FOUNDATION NOTES:

GENERAL: Notes

Details

Public school building, WPA era. Deteriorated lintels on north portal

EXTERIOR: Notes

Details

Additionally, there is a large access ramp with pipe railings at the building's southeast corner. Asphalt parking and student drop off areas stand at the building's north and east side. Chain link fencing and low coyote landscape-related fencing separates the grassy yard

ROOF: Notes

Details

**Flat Parapet
Canales
Flat**

DOORS: Notes

Details

wide double-leaf metal unit with a large area of undivided glass, and a stationary transom window.

WINDOWS: Notes

Details

On the north elevation, in the area of the post-1957 addition, windows are multi-lite steel units which have been sealed so that they no longer operate.

**Double Hung
Divided Light**

PORCHES/PORTALES: Notes

Details

Northwest and northeast corners - secondary entrances

**Exposed Lintels
Corbels
Exposed Vigas
Round Posts**

CHIMNEYS: Notes

Details

Not Available

EXTERIOR WALLS : Notes

Details

Not Available

LANDSCAPING: Notes

Details

Not Available

OTHER SIGNIFICANT FEATURES Describe unique features.)

[Empty box for other significant features]

MODIFICATIONS: (For each entry, indicate source of the date. Enter "surveyor" if it is your own. If prior survey, give date.)

[Empty box for modifications]


PRIMARY ARCHITECTURAL STYLE:

Public school building, WPA era. Deteriorated lintels on north portal

Spanish-Pueblo Revival

SITE PLAN:

(Include footprint of building, porches and balconies, major landscape features, associated properties, walls, fences, gates, nearby roads, driveways, and north arrow.)



LOCATION OF, AND AVAILABLE DOCUMENTS

(Plans, histories, oral histories, maps, aerial photos, bibliographic references, etc. and where they can be found.)

[Empty box for location of documents]

SITE PLAN NOTES:

Site. Base map provided by Taos GIS. NTS.

ATTACHED OR ASSOCIATED PROPERTIES: (List and describe. Indicate whether surveys exist for these and provide survey numbers if known.)

DESCRIPTION OF ATTACHED OR ASSOCIATED PROPERTIES

1939 Sanborn Maps reflect the area in which this building stands. It was occupied by the Taos High School to the north of the subject structure, and the recreation hall, Presbyterian church, and Presbyterian Mission School, which stood to the west of Enos Garcia School. The

IF SO, ARE THEY ELIGIBLE FOR LISTING?: None



2005 Survey Photo 3



2005 Survey Photo 4