

Historic Cultural Properties Inventory (HCPI) Base Form (FORM 1)

Historic Preservation Division, New Mexico Office of Cultural Affairs

For HPD Office use only: HCPI No. District No. NRHP: SRCP: Criteria: A B C D

NAME OF PROPERTY: **Paseo del Pueblo Norte 125 - Taos Inn Storage Building**

LOCAL REFERENCE NUMBER: **2005113**

LOCATION OF PROPERTY:

UTM ZONE:

CITY OR TOWN:

UTM EASTING:

COUNTY:

Taos

UTM NORTHING:

DATE OF SURVEY:

2/6/2005

PREVIOUS SURVEY?

Not Available

PREVIOUS SURVEY DATE:

Not Available

NAME OF PROJECT:

2005 CLG Survey

PHOTOGRAPH:

ROLL NUMBER:

FRAME NUMBER:

NEGATIVE LOCATION:



PROPERTY TYPE:

PHOTOGRAPH VIEW:

DESCRIPTION OF PROPERTY:

The detached storage building located at the southeast corner of the property at 125 Paseo de Pueblo Norte is a single story stuccoed structure with a flat parapet. Windows are small fixed single-lite units recessed into the north elevation. There are three stepped wing walls which extend from the north elevation. A single leaf metal clad paneled entry door on the north elevation. The building fronts the dirt parking lot that serves the Inn. The building has an attached wooden shed on the east with a corrugated metal roof. It sits immediately to the north of a detached storage building that serves 119 Kit Carson Road.

CONSTRUCTION DATE KNOWN? **Yes** SOURCE FOR CONSTRUCTION DATE:

CONSTRUCTION DATE: to

SIGNIFICANT MODIFICATIONS?

NOTES ON CONDITION:

WHO USES THE PROPERTY?:

SETTING:

RELATIONSHIP TO SURROUNDINGS: **Similar**

IF URBAN SETTING, NATURE OF IT:

COMMENTS ON SURROUNDINGS:

ADDITIONAL PERSPECTIVE: (Photo, drawing, footprint, etc.; indicate north arrow when possible)

[Large empty rectangular box for additional perspective]

NOTES ON ADDITIONAL PERSPECTIVE:
(If photo, include photo info, as in #10)

SURVEYOR BUSINESS NAME:

OWNER OR OTHER KNOWLEDGEABLE PEOPLE:

SURVEYOR FIRST NAME:

SURVEYOR LAST NAME:

SURVEYOR STREET ADDRESS:

IS THE PROPERTY ENDANGERED?: NO

SURVEYOR CITY:

HOW IS THE PROPERTY ENDANGERED?:

SURVEYOR ZIP CODE:

[Empty rectangular box for surveyor zip code]

SURVEYOR TELEPHONE:

SURVEYOR EMAIL:

SIGNIFICANCE TO CURRENT COMMUNITY:

DESCRIPTION OF COMMUNITY SIGNIFICANCE:

OTHER INFORMATION OF INTEREST: (Such as historical, legendary, structural, former ownership, etc.)

[Large empty rectangular box for other information of interest]

Individual Building Status

IS PROPERTY INDIVIDUALLY LISTED ON A REGISTER?:

INDIVIDUALLY LISTED ON SRCP?: NO

INDIVIDUALLY LISTED ON NRHP?: NO

IF NOT LISTED, IS IT ELIGIBLE?:

IF ELIGIBLE, WHY?:

[Empty rectangular box for eligibility reason]

Building Located In A Special Historic District?

IS PROPERTY IN SPECIAL HISTORIC DISTRICT? NO

DISTRICT NAME AND STATUS:

Taos Downtown Historic District - SRCP NO

La Loma Plaza Historic District - SRCP NO

Taos Historic Overlay Zone - Taos Only NO

Historic Cultural Properties Inventory (HCPI) Detail Form (Form 2)

Historic Preservation Division, New Mexico Office of Cultural Affairs >>Complete HCPI Form 1 before Form 2<<

For HPD Office use only: HCPI No. District No. LOCAL REFERENCE NUMBER:

NAME OF PROPERTY: LOCATION OF PROPERTY:

COUNTY: Taos

CITY OR TOWN:

DATE OF SURVEY: 1/1/1

ARCHITECTURAL AND CONSTRUCTION DETAILS

STORIES ABOVE GRADE? N/

CONSTRUCTION MATERIAL:

PRIMARY VISIBLE CONSTRUCTION MATERIAL:

NOTES ON VISIBLE CONSTRUCTION MATERIAL: The building fronts the dirt parking lot that serves the Inn. The building has an at

FOUNDATION:

" Not Available"

GENERAL: Notes

Details

The detached storage building located at the southeast corner of the property at 125 Paseo de Pueblo Norte is a single story stuccoed structure with a flat parapet.

EXTERIOR: Notes

Details

The building fronts the dirt parking lot that serves the Inn. The building has an attached wooden shed on the east with a corrugated metal roof. There are three stepped wing walls which extend from the north elevation. It sits immediately to the north of a detached

ROOF: Notes

Details

Not Available

DOORS: Notes

Details

A single leaf metal clad paneled entry door on the north elevation.

WINDOWS: Notes

Details

Windows are small fixed single-lite units recessed into the north elevation.

PORCHES/PORTALES: Notes

Details

Not Available

CHIMNEYS: Notes

Details

Not Available

EXTERIOR WALLS : Notes

Details

Not Available

LANDSCAPING: Notes

Details

Not Available

OTHER SIGNIFICANT FEATURES Describe unique features.)

Empty rectangular box for other significant features.

MODIFICATIONS: (For each entry, indicate source of the date. Enter "surveyor" if it is your own. If prior survey, give date.)

Empty rectangular box for modifications.


PRIMARY ARCHITECTURAL STYLE:

Hispanic Vernacular/Spanish-Pueblo Revival

The detached storage building located at the southeast corner of the property at 125 Paseo de Pueblo Norte is a single story stuccoed structure with a flat parapet.

SITE PLAN:

(Include footprint of building, porches and balconies, major landscape features, associated properties, walls, fences, gates, nearby roads, driveways, and north arrow.)



LOCATION OF, AND AVAILABLE DOCUMENTS

(Plans, histories, oral histories, maps, aerial photos, bibliographic references, etc. and where they can be found.)

Empty rectangular box for location of and available documents.

SITE PLAN NOTES:

Empty rectangular box for site plan notes.

Attached/Associated Properties Information Not Available